

Date: April 30, 2021

PCN No#: 043021-2

PCN Title: Additional new lead frame for SOT-563 Package

Dear Customer:

This is an announcement of change(s) to products that are currently being offered by Micro Commercial Components Corp(MCC) .We request that you acknowledge receipt of this notification within 30 days of the date of this PCN. Please refer to the implementation date of this change as it is stated in the attached PCN form. Please contact your local sales representative to acknowledge receipt of this PCN.

If you have any questions about PCN's products, please contact your local sales representative.

Sincerely,

MCC PCN Team



## **PRODUCT CHANGE NOTICE**

	Implementation Date	Last Time Buy Ship Date	Change Type	PCN No				
April 30, 2021	July 30, 2021	July 30, 2021	Additional new lead frame	043021-2				
TITLE								
Additional new lead frame for SOT-563 Package								
DESCRIPTION OF CHANGE								
To improve our current lead time , MCC added new lead frame for SOT-563 package products. Internal qualification process had been finished and the result showed that the parts had the same performances as the parts we shipped before.								
ІМРАСТ								
No change in datasheet electrical parameters and product performance. Table A: Lead frame comparison and package outline comparison.								
PRODUCTS AFFECTED								
Table 1: Affected Parts List								
WEB LINKS								
Terms And Conditions	s: https://w	ww.mccsemi.com/Home/Terms	AndConditions					
Terms And Conditions		/ww.mccsemi.com/Home/Terms. /ww.mccsemi.com/Contact/Inde						
	Contact: https://w		(					



Table /	A - Lead frame comparison and pac	ckage outline comparison	
	Old	New	
Lead frame (BAS40V-TP)		<b>by</b>	
Package outline			
	DIMENSIONS	DIMENSIONS	
	DIM INCHES MM NOTE	DIM INCHES MM NOTE	
	A 0.006 0.011 0.15 0.30	A 0.006 0.011 0.15 0.30	
	B 0.043 0.051 1.10 1.30	B 0.043 0.051 1.10 1.30	
	C 0.059 0.067 1.50 1.70   D 0.020 0.50 0.50	C 0.059 0.067 1.50 1.70   D 0.020 0.50	
	G 0.035 0.043 0.90 1.10	G 0.035 0.043 0.90 1.10	
	H 0.059 0.067 1.50 1.70	H 0.059 0.067 1.50 1.70	
	K 0.020 0.023 0.52 0.60	K 0.022 0.026 0.55 0.65	
	L 0.004 0.011 0.10 0.30	L 0.004 0.011 0.10 0.30	

Table 1 - Affected Parts List					
BAT54V-TP	BC847BV-TP	MMDT3906V-TP	2N7002V-TP		
MMBD4448V-TP	BC857BV-TP	EMD22-TP	SIX3134K-TP		
BAS16V-TP	EMZ1-TP	EMH10-TP	SIX3139K-TP		
BAS40V-TP	MMDT3904V-TP	2N7002KV-TP	SIX3439K-TP		