

# Micro Commercial Components Corp.

## Products End of Life Notification

Issue date: Nov-14<sup>th</sup>-2013

EOL No#: 111413

Last Buy Date :2014/6/1

Description and Purpose:

MCC has undergone a review of its core business and products , and determined to discontinue below products:

| Discontinued Devices | Possible Replacement | Discontinued Devices | Possible Replacement | Discontinued Devices | Possible Replacement |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| MB1505-BP            | N/A                  | MB501W-BP            | N/A                  | MP158W-BP            | N/A                  |
| MB151-BP             | N/A                  | MB502W-BP            | N/A                  | MP2505WGP-BP         | N/A                  |
| MB1510-BP            | N/A                  | MB504W-BP            | N/A                  | MP2510WGP-BP         | N/A                  |
| MB152-BP             | N/A                  | MB506W-BP            | N/A                  | MP251WGP-BP          | N/A                  |
| MB154-BP             | N/A                  | MB508W-BP            | N/A                  | MP252WGP-BP          | N/A                  |
| MB156-BP             | N/A                  | MP1505-BP            | N/A                  | MP254WGP-BP          | N/A                  |
| MB158-BP             | N/A                  | MP151-BP             | N/A                  | MP256WGP-BP          | N/A                  |
| MB354CA-BP           | N/A                  | MP1510-BP            | N/A                  | MP258WGP-BP          | N/A                  |
| MB5005-BP            | N/A                  | MP154-BP             | N/A                  | MP2505W-BP           | N/A                  |
| MB501-BP             | N/A                  | MP156-BP             | N/A                  | MP2510W-BP           | N/A                  |
| MB5010-BP            | N/A                  | MP158-BP             | N/A                  | MP251W-BP            | N/A                  |
| MB502-BP             | N/A                  | MP2505-BP            | N/A                  | MP252W-BP            | N/A                  |
| MB504-BP             | N/A                  | MP251-BP             | N/A                  | MP254W-BP            | N/A                  |
| MB506-BP             | N/A                  | MP2510-BP            | N/A                  | MP256W-BP            | N/A                  |
| MB508-BP             | N/A                  | MP252-BP             | N/A                  | MP258W-BP            | N/A                  |
| MB1510W-BP           | N/A                  | MP254-BP             | N/A                  | MP3505W-BP           | N/A                  |
| MB151W-BP            | N/A                  | MP256-BP             | N/A                  | MP3510W-BP           | N/A                  |
| MB152W-BP            | N/A                  | MP258-BP             | N/A                  | MP351W-BP            | N/A                  |
| MB154W-BP            | N/A                  | MP3505-BP            | N/A                  | MP352W-BP            | N/A                  |
| MB156W-BP            | N/A                  | MP351-BP             | N/A                  | MP354W-BP            | N/A                  |
| MB158W-BP            | N/A                  | MP3510-BP            | N/A                  | MP356W-BP            | N/A                  |
| MB2505W-BP           | N/A                  | MP352-BP             | N/A                  | MP4005W-BP           | N/A                  |

| Discontinued Devices | Possible Replacement | Discontinued Devices | Possible Replacement | Discontinued Devices | Possible Replacement |
|----------------------|----------------------|----------------------|----------------------|----------------------|----------------------|
| MB2510W-BP           | N/A                  | MP354-BP             | N/A                  | MP4010W-BP           | N/A                  |
| MB252W-BP            | N/A                  | MP356-BP             | N/A                  | MP401W-BP            | N/A                  |
| MB254W-BP            | N/A                  | MP4005-BP            | N/A                  | MP402W-BP            | N/A                  |
| MB256W-BP            | N/A                  | MP401-BP             | N/A                  | MP404W-BP            | N/A                  |
| MB258W-BP            | N/A                  | MP4010-BP            | N/A                  | MP406W-BP            | N/A                  |
| MB3505W-BP           | N/A                  | MP402-BP             | N/A                  | MP408W-BP            | N/A                  |
| MB3510W-BP           | N/A                  | MP404-BP             | N/A                  |                      |                      |
| MB351W-BP            | N/A                  | MP406-BP             | N/A                  |                      |                      |
| MB352W-BP            | N/A                  | MP408-BP             | N/A                  |                      |                      |
| MB354W-BP            | N/A                  | MP1505W-BP           | N/A                  |                      |                      |
| MB356W-BP            | N/A                  | MP1510W-BP           | N/A                  |                      |                      |
| MB358W-BP            | N/A                  | MP151W-BP            | N/A                  |                      |                      |
| MB5005W-BP           | N/A                  | MP152W-BP            | N/A                  |                      |                      |
| MB5010W-BP           | N/A                  | MP154W-BP            | N/A                  |                      |                      |